


Product Bulletin

Date: October 11, 2006

GTHB & GTHC Return Air Dimension Error IOM Literature

An error in the Installation Manual and Operating Instructions for the GTHB and GTHC - Natural Gas and Propane Gas High Efficiency (Condensing) Warm Air Furnaces has been identified for the return air opening. The literature incorrectly indicates the Return Air dimensions. The correct Return Air dimensions (D x E) are 14" x 22".



The affected literature can be identified by the Part Numbers:

GTHB – 240005603, Rev. A [08/06] GTHC – 240006339, Rev. A [08/06]

The Product Brochure is correct. The IOM will be updated.

We are sorry for any inconvenience. If you have any further questions, please contact ECR International Technical Support at 800-325-5479.